County(ies):

Shelby

7994-1535-54

TDOT Construction No.

# TENNESSEE DEPARTMENT OF TRANSPORTATION EROSION PREVENTION/SEDIMENT CONTROL INSPECTION REPORT

TDOT EPSC INSPECTION FORM Rev. Feb 2010.

Reason For Inspection:

NPDES Permit (NOC) #:

Contractor:

TNR153299

Acuff Enterprises Inc.

1st Weekly

Number of New

Corrective Actions:

0

2nd Weekly

1.23.12 Are corrective actions required by this inspection report (Y/N): Number of Recurring Number of Un-Corrected Number of New Corrective Actions: Sediment Releases: Sediment Releases:

I certify, under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated information presented. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, I cerify that inspections of storm water discharge points (outfalls) and of erosion and sediment controls have been performed as recorded in the table above. I certify that erosion and sediment controls in the drainage area of the identified outfall where installed as planned and designed in working order as recorded in the table above. Tam aware that there are significant penalties for submitting false information, including the possibility of fine and impresonment for knowing violations

Wolf River Blvd.

101615

TDOT Contract No.:

State Roule (SR) / US Route or Road Name and Description:

TDOT PIN:

COG EPSC Inspector and Title (print or type):	Signature:
Gerald "Jerry" Stanfill	Gerald Stanfell
Contractor EPSC Inspector and Title (print or type):	Signature:
Toin Acuff	Jon hands
COG EPSC Project Manager	Signature:
(print or type):	
Timothy Bierdz	3206

0

TDOT EPSC Inspection Weekly Rainfall Data Lon

		Predicted	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall		TDOT/Contractor Agrees with Inspection Report:
Date	Day of Week	Precipitation	Gauge 1	Gauge 2	Gauge 3	Gauge 4	Gauge 5	Gauge 6	Duration	NO or YES
		(%)	(in)	(in)	(in)	(in)	(in)	(in)	(hr)	If No, explain and initial:
1.22.12	Sunday	30			N/A	N/A	N/A	N/A		
1.23.12	Monday	10	0.60	0.50	N/A	N/A	N/A	N/A	2.5	
24.12	Tuesday	10			N/A	N/A	N/A	N/A		
. 25.12	Wednesday	80			N/A	N/A	N/A	N/A		
26.12	Thursday	60			N/A	N/A	N/A	N/A		
.20.12	Friday	30	0.20	0.20	N/A	N/A	N/A	N/A	1.5	
.21.12	Saturday	20			N/A	N/A	N/A	N/A		
	Sunday				N/A	N/A	N/A	N/A		
	Monday				N/A	N/A	N/A	N/A		
										(Additional pages may be attached, if needed)

Predicted Precipitation Source

'www.weather.com

Page 1 of 6

\* TOO WET TO WORK CONDITIONS

State

State/US	S Route	or Road	Name

Wolf River Blvd.

TDOT Construction No	
	•

	1-353	

TDOT Contract No.:	
--------------------	--

**CONDITION CODES** 

Date	1/23/2012

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	1	14+14	LT	1/23/2012		22,35	FM,W	Monitoring outfall.
1A	1	21+50	RT	1/20/2012		41	FM,W	Const. of RCBC Pedestrian Underpass in progress, No activity during inspection.
1B	1	22+00	RT	1/6/2011		41	FM,W	Correct washout and reset filter socks.
1C	1	21+00	LT	11/7/2011	T = 10-6-11	12,15,35,41	S,W	Currently stable, monitoring BMP's
2A	1	33+50	LT,CL	1/20/2012		12,15,16	S,W	Currently stable, monitoring BMP's
2B	1	35+50	LT	1/20/2012		16,24	FM,W	Weekly cleaning for stream crossing required, until further notice.
3	1	34+50	LT	10/27/2011		16	FM,W	Outfall slopes north of temp. stream crossing are showing signs of failure.
4	1	40+00	RT	12/12/2011	T = 10-24-11	15,16,43	S,W	Currently stable at this time.
5A	1	49+00	RT	1/6/201		16,33	S,W	Currently stable, monitoring BMP's
5B	1	50+00	RT	12/19/2011		9,16,33	S,W	Currently stable, monitoring BMP's

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

## Temporary Silt Fence / Filter Barrier Temporary seeding with Mulch Excess Dirt Removed from Rdwy. Daily M Maintenance Temporary Diversion Berm or Ditch 2 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) Temporary Slope Drain 3 17 Erosion Control Blanket 31 Ditch Liner Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing Cleaning Needed Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures Straw Bale Check 7 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions Sand Bags 8 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence Sediment Trap / Basin 9 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling CM Corrections currently being made 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O31): 14 Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Subgrade 42 **Bridge Construction** Other (O#2): Stream Realignment Other (O#3):

OF.	XY	1657	
GRI	cut	EURI (	
	імеч 796		<i>y.</i>

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:	
------------------------------	------------------	------------------------	---------------	--------------------	--

Date	1/23/2012

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT	1/20/2012		16,24,33	CM,FM,W	Silt fence incomplete at this time. Weekly cleaning for stream crossing required.
6	1	56+00	LT	1/20/2012			FM,W	No activity at pond during inspection.
7	1	60+00	RT	10/24/2011		16, 33	s,w	Currently stable, monitoring BMP's.
8A	1	73+00	RT	1/20/2012	-	16,24,42	FM,W	Weekly cleaning for stream crossing will be required, until further notice.
8B	2	75+50	RT	9/29/2011		16,35,41	FM,W	Currently Stable, monitoring BMP's.
8C	1	71+00	LT	1/20/2012		16,35,42	S,W	Bridge construction zone. monitoring BMP's.
8D	2	75+50	LT	1/20/2012	T = 10-3-11	16,35,42	CM.W	Bridge 2, Abutment 2 at north corner and bank slopes require stabilization.
8E	1	71+50	LT					The area has not been disturbed.
9A	2	80+00	RT	9/29//11	T = 10-3-11	6,15,33,35	S,W	Currently stable, monitoring BMP's.
9B	2	80+00	LT	9/29//11	T = 10-3-11	15,16,17,,35	S,W	Currently stable, monitoring BMP's.

# **EROSION AND SEDIMENT CONTROL MEASURE CODES**

## **CONDITION CODES** Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch Excess Dirt Removed from Rdwy, Daily Maintenance M 2 Temporary Diversion Berm or Ditch Temporary Mulch 16 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing C Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence 1 Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling CM Corrections currently being made 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O31): 14 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#2): Other (O#3):

State/US Route or Road	Name

River	

	TDOT Construction No.:	79954-3537-54
--	------------------------	---------------

TDOT	Contract No.:	
1001	Contract No	

Date	1/23/2012	

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	9/29/2011	T = 10-03-11	15,16,20,33	s,w	Currently stable, monitoring BMP's.
10A	2	85+00	RT	9/29/2011		15,16,35,41	FM,W	Repairs will be needed after job site dries out. Note: Too wet to install structural backfill
10B	2	85+00	RT	9/29/2011		15,16,35,41	FM,W	Repairs will be needed after job site dries out. Note: Too wet to install structural backfill
10C	2	85+50	LT	11/14/2011		15,16,35,41	FM,W	Repairs will be needed after job site dries out. Note: Too wet to install structural backfill
10D	2	84+50	LT	1/6/2012	8	15,16,35,41	s,w	Currently stable, monitoring BMP's.
11A	2	92+50	RT	11/14/2011		35,41	S,W	Repairs will be needed after job site dries out. Note: Too wet to install structural backfill
11B	2	92+50	LT	1/6/2012		10,32,35,41	S,W	Currently stable, monitoring BMP's.
11C	2	92+00	LT	10/6/2011		10,32,35,41	S,W	Currently stable, monitoring BMP's.
	1	11+28	LT	1/23/2012		19,35	FM	Daily cleaning is required, until further notice.
	1	13+40	RT	1/20/2012		23,29,30	FM,W	Daily cleaning will be required, until further notice.
	1	107+75	CL	1/20/2012	EACURE CORES	23,29,30	FM,W	Daily cleaning will be required, until further notice.

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

Temporary Stream Diversion

Preserve Natural Resource / Buffer Zone

Mineral Aggregate Base on Subgrade

## Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch 2 Temporary Diversion Berm or Ditch Temporary Mulch Temporary Slope Drain 17 Erosion Control Blanket Rock Check Dams 18 Flexible Channel Liner 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection 6 Sediment Removal 20 Riprap Outlet Structure 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 8 Sand Bags Curb, Gutter, or Storm Sewer Protection 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 10 Temp Sediment Filter Bag / Dewatering Temporary Stream Crossing 24 11 Polyethylene Sheeting Turbidity Barrier / Silt Boom

26

27

31	Ditch Liner
32	Rock Silt Screen
33	Temporary Silt Fence with Backing
34	Enhanced Silt Fence
35	Sediment Tube
36	Sediment Dam
37	Concrete Washout, other pollution Issues
38	Berm (soil, riprap, rock)
39	Gabion
40	Sheet Pilling
41	Haul Road
42	Bridge Construction

29 Excess Dirl Removed from Rdwy. Daily

30 Haul Roads Dampened for Dust Control

M	Maintenance
U	Upgrade Needed (Failure Noted)
R	Replacement Needed
FM	Future Maintenance
С	Cleaning Needed
1	Increase Measures
W	Too Wet to Work Conditions
RO	Repeat Occurrence
SR	Sediment Release
FS	Final Stabilized
S	Stable (No Action Needed)
CM	Corrections currently being made
Other (O31):	

**CONDITION CODES** 

Machined Rip Rap

Permanent Seeding with Mulch or Sod

Geotextile

12

13

	OF THE ST	
18	AGRICULTURE	
	ACARCO AND	
1	1796+	

State/UL	S	Route	or	Road	Name:	
State/O	v	Noute	U	Nuau	ivallie.	

W	10	f	R	ive	r	٦l	h

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date	1/23/2012

	2000		Service and the service and		Date of	Existing	1	
Outfall Name	Rain	Approx.	LT, RT or	Date Last	Stabilization	EPSC	Current	
or Station No.	Gage	Station No.	Centerline	Disturbed	and Code	Control	Condition	Corrective Action(s) or Comments
*(Existing	No.	From / To			T = Temp.	Measure	Codes*	
Structure)					P = Perm.	Codes*		
* 109+51	2	Cost side of MDD	DT	4/00/0040				Daily cleaning will be required, until furthe
109+31		East side of WRB	RT	1/23/2012		19,22	FM	notice.
* 100 . 11	0	South side of	-				20000000	Daily cleaning will be required, until furthe
* 109+11	2	Farmington	RT	1/23/2012		19,22	FM	notice.
* 10.00	,	North side of				2000 40000		Daily cleaning will be required, until further
* 12+80	1	WRB	LT	1/23/2012		19,22	FM	notice.
		Walking Trail						
	1	36+00	LT	7/20/2011	T = 7-20-11	5,35	S,W	Currently stable, monitoring BMP's
	1	Sta. 29+50 Slope	LT	7/20/2011	T= 9-01-11	10	0.147	
			LI	112012011	1-9-01-11	16	S,W	Currently stable.
		Sta. 13+40 -		20 20 202 20				Haul roads dampened frequently for dust
		Sta. 107+75	LT, RT or CL	10/13/2011		30	S,W	control, until further notice.
	2	76+50 - 103+46	RT	9/29/2011	T = 10-03-11	15 10 25	0.14/	0 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4
		70.00-100140	IXI	9/29/2011	1 - 10-03-11	15,16,35	S,W	Currently stable, monitoring BMP's
	2	92+50 - 107+00	LT	9/29/2011	T = 10-03-11	15,16,35	s,W	Currently stable, monitoring BMP's
					1.0			Daily cleaning will be required, until further
	1	6+75	LT	1/23/2012		19,22	FM	notice.
	1	27+00	RT	10/3/2011	T= 10-03-11	15,16	S,W	Currently stable, monitoring BMP's
	1	34+00	RT	8/25/2011	T= 8-25-11	16	S,W	Currently stable, monitoring BMP's
EROSION AND SEDIMENT CONTROL MEASURE CODES						CONDITION CODES		

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

## Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily M Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed Rock Check Dams Flexible Channel Liner 18 32 Rock Silt Screen FM **Future Maintenance** 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing C Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 **Enhanced Silt Fence** Increase Measures Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release Temp Sediment Filter Bag / Dewatering 10 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting Turbidity Barrier / Silt Boom 25 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Other (O31): Sheet Pilling 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): 14 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade Bridge Construction Other (O#3):

	OF THE ST
6	ACRICUATURE
./	Offmer 1796

0 id Name:	Wolf River Blvd.	
0 id Name:	vvoit River Biva.	

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date

1/23/2012

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
	1	21+33 - 26+00	LT	10/10/2011	T = 10-6-11	15,16,35,41	S,W	Currently stable, monitoring BMP's.
	_ 1	21+33 - 26+00	RT	10/10/2011	T = 10-6-11	15,16,35,41	S,W	Currently stable, monitoring BMP's.
	1	25+00	LT	12/14/2011	T = 10-6-11	15,16,33,35,41	S,W	Currently stable at this time.
	1	25+00	RT	9/29/2011	T = 10-6-11	15,16,33,35,41	S,W	Currently stable, monitoring BMP's.
	1	27+50	RT	10/6/2011	T = 10-6-11	15,16,33,35,41	S,W	Currently stable, monitoring BMP's.
	1	31+90	RT	9/29/2011	T = 10-6-11	15,16,35	S,W	Currently stable, monitoring BMP's.
	1	15+60	LT & RT	1/23/2012		15,16,33,35	FM,W	Installation of headwalls are in progress.
* 108+37		North side of WRB	LT	1/23/2012		19,22	FM	Daily cleaning will be required, until further notice.
	1	23+00 - 26+00	RT	9/29/2011	T = 10-6-11	33,41	S,W	Currently stable, monitoring BMP's.
	1	48+50	RT	1/23/2012		33	FM, <b>W</b>	Correct washout and repair silt fence.

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

## **CONDITION CODES** Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily M Maintenance Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance 5 Brush Barrier Catch Basin / Storm Inlet Protection 19 Temporary Silt Fence with Backing C Cleaning Needed Sediment Removal 20 Riprap Outlet Structure Enhanced Silt Fence Increase Measures Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues Sediment Release Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Sub grade **Bridge Construction** Other (O#3):